

Relay Job

Nº 5562

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-22-50

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 125' 3 1/2' Deep at 1

HOUSE NO. 216

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 125'

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN See Sketch NAME OF CONTRACTOR Remley


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Sta. 1+25 is 6x4 Y on Main

Sta. 1+31 is end of relaid

Main Sewer from M. H. at North & Lewis Pl. N.E.

4" Lateral relaid from Main Line 19' towards house.



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 1+25

REMARKS: 2-26-51

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 5562
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/30 1924

RECEIVED OF

26
FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.