## Nº 5567 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO. 25/8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	· Flood
WAS LATERAL AT CURB?	<ul> <li>[1] A. Common of the state of t</li></ul>	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR REIN / CY	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
Lincoln W	ay. W.	- 5'deng
or the Millian was 🦍 -	and the state of t	
one parimeter and entre of the the	and the second of the second o	
	a de la composição de la Composição de la composição de la composiç	8 das
		— WY# :/ C
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	206051
REMARKS: Belaid 10	Million 14 . Louising of Wall-live for efficient	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,
Thomas and a
RECEIVED OF FEE OF S
and the first of the state of t
FOR WHICH PERMISSION IS GRANTED
TO TAP SEWER, ON THE
and the first of the form of the second of t
of french way have type of STREET True.
THE PREMISES BEING LOT NO. 106 , HOUSE NO. 3518
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO 2222 DILLY DACCED BY THE COMMENT

NAME OF CONTRACTOR / LEMES 4

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.