## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 5568 AND SIGNED WHEN RETURNED.

DATE INSPECTED 9 25 -50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 436	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE CONTROL OF THE CONTROL OF T
WAS LATERAL AT CURB?	and gradients of the control of the set of t
WAS ATTACHED TO MAIN Below to Me	NAME OF CONTRACTOR ACM / CY
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.
16TH 5to N	Los for the second seco
The second secon	The first of the first of the state of the s
eren saminar et er er er skrivet et en en er	The second secon
	transfer of the factor of the contract of the contract of
	4 day
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SIGNED Orlan Elevery	
INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS: 1 + ald 1	real Zeredelle ar ne dalare at teoristical formittes

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	PERMIT TO TAP SEWER	
	Massillon, Ohio, 1/30	
	RECEIVED OF A. Remiler FEE OF S	2
FOR	WHICH PERMISSION IS GRANTED E. W. C. W. C. C.	- h- : -
тот	F (An) SEWER, ON THE	
OF_	16 th 76 AVE. TYPE OF STREET Lave d.	9 - 1
THE	REMISES BEING LOT NO. 5850. , HOUSE NO. 436	
4	TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY	Col
RUL	S OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.