

S.R. 14-48

Nº 5575

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.



DATE INSPECTED 2-1-50IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 2226SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 18' up stream

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Reimley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Claremont Ave NW

SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-6-51

REMARKS:

tapped in.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5575

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/30 19

RECEIVED OF

R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

W. B. Ripscomb

TO TAP

San

SEWER, ON THE

OF

Claremont Mt.

AVE.,

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

5998

HOUSE NO.

2226

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.