

5.K.8 - P.7

Nº 5576

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-12-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 148

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH Tapped in M.H. @ Vermont + 19th

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

19TH ST, S.E.

← N



SIGNED _____
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 2-6-51

REMARKS: tapped in M.H.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o. 5576 PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/30 19

RECEIVED OF

R. Remley

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

W. M. Smith

TO TAP

San

SEWER, ON THE

E

OF

19th & E

AVE.
ST.

TYPE OF STREET

Wile

THE PREMISES BEING LOT NO.

6234

HOUSE NO.

158

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.