

Nº 5587

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-27-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 814

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


111' 4' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R.F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

3/29/51

REMARKS:

№ 5587

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

3/12 19

RECEIVED OF

Paul E. Ringley

FEE OF \$

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

Paul E. Ringley

TO TAP

Sanitary

SEWER, ON THE

North

OF

Bennington NE

AVE.

TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

8525 + Pt 8524

HOUSE NO.

814

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Diana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.