FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-20-5/	IF SO HOW AND LOCATION FROM	
	FIRST MANHOLE DOWN STREAM	
HOUSE NO. 529		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 142	5'dech
WAS LATERAL AT CURB?	in and in the new Agent Book by the leading of the second	
WAS ATTACHED TO MAIN		
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	[· · · · · · · · · · · · · · · · · · ·
25 TH 5		5 dech
	rando (1980) especial de altrasecto de las primeses de las comeses de la comese della comese de la comese de la comese de la comese de la comese della comese del	5 dough
		and the second s
SIGNED OF LAND	FILED AT ENGINEER'S OFFICE	2/29/61
INSPECTOR FOR CI		

5589

NO 5589 PERMIT TO TAP SEWER

MASSILLON, OHIO, $\frac{3}{2}$ 0 The $\frac{3}{2}$ 19
RECEIVED OF U Juana FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED Q.C. h. Faddler
TO TAP Cantany SEWER, ON THE West
OF 25 th 11. E AVE., TYPE OF STREET dela
THE PREMISES BEING LOT NO. 94324 , HOUSE NO. 529

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.