Nº 5599 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-1-5	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1313		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	52 Dees
WAS LATERAL AT CURB? VES		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DLAN	<u>a</u>
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	
	19/5' Deep	est.
,	Committee of the second of the	
52 Deep	(12' W. Curb	Main Sewer
SIGNED Rit, Smoth	FILED AT ENGINEER'S OFF	5-10 -1
REMARKS: SEWE AID	in this manner	because lat
at N. End of 13	st could not be	Sound.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5599 PERMIT TO TAP SEWER

the second of th
MASSILLON, OHIO, 19
RECEIVED OF A Diana FEE OF 5 2°
FOR WHICH PERMISSION IS GRANTED WITHOUT Julner
A A A A A A A A A A A A A A A A A A A
TO TAP SEWER, ON THE
Sunkerst n E AVE. TYPE OF STREET Pared.
THE PREMISES BEING LOT NO. 10736 , HOUSE NO. 13/3
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
\mathcal{N}

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.