## Nº 5600

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-28-51	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  231  227  227  227  237
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIAMA
SHOW BY DIAGRAM RELATION OF LATER	
	/ Decp 2/10'
and the same and a second of the same and th	
	12 Drepul6 SW. Curb
SIGNED R. J. Junglu INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 5-12-51
PFMARKS.	and the second of the second o

## TA ALL STOFFICE OF THE DIRECTOR OF PUBLIC SERVICE

- Maria 2000 a min Tana ChekWI.	T TO TAP ŞEWER
e in marchine de la companya de la c	4/27
	SSILLON, OHIO,
FOR WHICH PERMISSION IS GRANTED WHILL	Graler FEE OF 5.0
TO TAB JAM. SEWER, ON	THE
of emlast n. Eave. TYPE OF	STREET Tanel.
107.35	1307

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

IAME OF CONTRACTOR Lana

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.