## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-10-51	IF SO HOW AND LOCATION FROM FIRST MANHOLE SECTION STREAM	75	9 Deep.
House No	<b>م</b> ن .		
SIZE OF PIPE USED P	DISTANCE FROM FIRST MANHOLE  BOWN STREAM TO DITCH AT CURB LINE AND DEPTH	74'	9' Deep.
WAS LATERAL AT CURB? No	and the second of the second section where	to provide a supplied to the state of	•
WAS ATTACHED TO MAIN TA Pred.	NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SE	RVED.	
en Santager en de la deservació de la composition della compositio		27'	-8, Deeb
			75'
SIGNED Ralph Griesher	FILED AT EN	28 9'Drep 5 GINEER'S OFFICE	<del>-</del> 0
INSPECTOR FOR CITY	geddiese Steet food des 11 pe	ablice in Alexa 5	-14-51

## WAR LEGISLE WHEEL IN A CORFICE OF THE DIRECTOR OF PUBLIC SERVICE

	Nº 5606 PERMIT TO TAP SEWER
	the second s
!	MASSILLON, OHIO,1
	RECEIVED OF AND FEE OF S
	FOR WHICH PERMISSION IS GRANTED (11) (1) (1)
	TO TAP SEWER, ON THE
	DELLY MAN BULLIAVE., TYPE OF STREET MILE
	THE PREMISES BEING LOT NO. 33 18/40, HOUSE NO.
:	Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counc
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.