

Nº 5611

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-5-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

202

10' deep

HOUSE NO. _____

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Astoria

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

30TH ST. N.W.

N.

10' deep

9

7' deep

50'

12'

202

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-29-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5611

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/16 1915

RECEIVED OF H. Aston

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED Paul Halten

TO TAP San

SEWER, ON THE E.

OF 30th Ave

AVE., TYPE OF STREET Dist

THE PREMISES BEING LOT NO. off 192-12

HOUSE NO. _____

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Aston

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.