## Nº 5616

# FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-2/- 5/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	92	10'dee/,
HOUSE NO. 707		,	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB7	and the second of the second o	Diameter (Vitalia)	
	NAME OF CONTRACTOR DA	ana	<u> </u>
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.		1
Matthias 1	Aver NE	7	2
la produce de la production de la servicio de la production de la servicio de la servicio de la servicio de la La companya de la co		31/200	
Almora, no primer de messo en la constalión de area y Portes entres. Con	i designi da deserbatika in propositional da deserbatika da deserbatika da deserbatika da deserbatika da deserbatika de deserbatika de deserbatika de	• 1	
	V V	10 desh 2	92
The Elm	and the second s	Tapped	in . 3-51
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEE	···	
REMARKS:			·

### SAME DE REAL OF THE PUBLIC SERVICE

# Nº. 5616 PERMIT TO TAP SEWER

an energy was a six was as an in the first of the figure constitution of the first
Massillon, OHio, 18
RECEIVED OF FEE OF \$2
FOR WHICH PERMISSION IS GRANTED ALATAAN
TO TAP SEWER, ON THE
OF MITTING TYPE OF STREET CILLI
THE PREMISES BEING LOT NO. 5324, HOUSE NO. 707
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
a Diana

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.