

Nº 5620

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6/1/51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1629

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 65' 9'deep


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Byron Ave. S.W.



SIGNED

John E. Hanner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-14-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5620

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/26/51 15RECEIVED OF John E. LomasFEE OF \$ 2⁰⁰FOR WHICH PERMISSION IS GRANTED John E. LomasTO TAP Sanitary SEWER, ON THE SouthOF Byron Ave. S.W. AVE., TYPE OF STREET Hard surfaceTHE PREMISES BEING LOT NO. 8124-8125, HOUSE NO. 1629WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR A. J. D.iana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.