

Nº 5622

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-16-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

76' from M.H. in 17th

HOUSE NO. 225

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? See Sketch

WAS ATTACHED TO MAIN "Y" cut in

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. J. Shuler
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 6-1-51

REMARKS: Broke pipe in tapping so put in new "Y."

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5622

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/28/57 19RECEIVED OF A. J. OranaFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED George OrphanTO TAP SanitarySEWER, ON THE WestOF 17th St NEAVE.,
ST.,TYPE OF STREET Land rampTHE PREMISES BEING LOT NO. 9055HOUSE NO. 225

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Orana

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.