

8
7-

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 5625 AND SIGNED WHEN RETURNED.**

DATE INSPECTED 6-5-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1867

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH Tapped in M.H.


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

VERMONT AVE. S.E.



19TH ST. S.E.

SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-14-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5625

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29 19

RECEIVED OF

E. W. Hostetter

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

E. W. Hostetter

TO TAP

Sanitary

SEWER, ON THE

South

OF

Pearmont St.

AVE.,

TYPE OF STREET

Hard

surface

THE PREMISES BEING LOT NO.

6237

HOUSE NO.

1867

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Diana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.