1000	, S. Y.	- 3		
$N_{ m o}$	 5	6	2	6

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 32-AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-29-51	_ IF SO HOW AND LOCATION FROM _ FIRST MANHOLE DOWN STREAM _		
HOUSE NO. 336			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	272	7'Deep
WAS LATERAL AT CURBI YES	on de la companya de En la companya de la	in who with the second of the	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Keuper	
SHOW BY DIAGRAM RELATION OF LAT		RVED.	N
	$\frac{A}{q} = \frac{1}{2}$	1 48-	
renga saud a di Hoen su strandisu aad ultivas punast. Ta	្លាយ មាន ជាស្ថាយ គឺ នៅ ជាជា ជាជាស្វាយ នៅ	2 Tabee	P
		32	
ili. Ligina de la composição d	7'Deepy	1 / 1 / 1 / 1 1 1 1 1 1 1 1 1 1 1 1 1 1	N. Gutter L
$\mathbb{R} \supset \mathbb{A}$		1 - EM	N. Gutter Lam Stwer
SIGNED INSPECTOR FOR C	FILED AT EN	GINEER'S OFFICE	w. 5/
REMARKS:		iditud bardinya." (1	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5626 PERMIT TO TAP SEWER

			f · · ·
	nata Maral∤tari	<i>□</i> //	
00	MASS	ILLON, OHIO,//	19
10/20 1	Service Assessment	ga Tarahaman da karangan sa	Same of the
RECEIVED OF	LA LARLE	<i>'U</i>	FEE OF \$20
FOR WHICH PERMISSION IS GRANTED	Lathe	•	
A.			. The Arthur Manager of the
1 / 1 / 1	•	Y = Y Y	
TO TAP	SEWER, ON TH	E / 1/2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<u> Santa in Bakir</u>
1 5 6			A second trees
Lake) 1160	AVE., TYPE OF ST	I(I)	$V_{A} \supset V_{A} = 0$
	ST., TYPE OF ST	REET	<u></u>
رب اس	150	a	2/
THE PREMISES BEING LOT NO.	109	, HOUSE NO	<u> </u>
	/		.,
WORK TO BE DONE IN ACCORDANCE V	WITH OPDINANCE NO 2	222 DULY BACCED	DV THE CITY CANNA
	1 4	LOES, DULY PASSED	BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC	SERVICE.	•	•

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.