## 5634

## FIGURE 18 AN FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-22-5/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 15/5	State of the state	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8'de0/2
WAS LATERAL AT CURBY Y 5	. The company of the	, ,
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Diana	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
Lennox A	Je W.E. Janes Jane	3'deg
i kalendaria i li ekonomik kumeni dadi yedi. Tan		Ho 8 dach.
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE_	123
REMARKS:		

## A STATE OF THE DIRECTOR OF PUBLIC SERVICE

ar of	Nº 5634 PERMIT TO TAP SEWER
****	RECEIVED OF A HARDA FEE OF SA
•	FOR WHICH PERMISSION IS GRANTED
	OF ANE. TYPE OF STREET ( ) Carl
	ST. TYPE OF STREET 151

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE,

NAME OF CONTRACTOR A. HARANO

Note. This permit/covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.