## Nº 5641

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-20-51 HOUSE NO. 1807	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	44.	6'dach
WAS LATERAL AT CURB? Ver	en an indicator and a subsection of the subsecti	ente pentro en encar	·
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR	Remley.	
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SE	RVED.	
Lindbergl	The second of the second second	Commence of the second of	17
		deep	17 44
SIGNED INSPECTOR FOR CITY	FILED AT EN	GINEER'S OFFICE	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NY 5641V	PERI	MIT TO	TAP S	EWER	
	rannwaren (b. 1985) 1. septim veleta en en en	Massillon, C	оню, 6/1	8	.1! C
RECEIVED OF	1 den	VIII		FEE OF S	
TAPO (Jan)	SEWER	, ON THE			
Lind Resilo	7) (AVE. TYPE ST.,	٦	der	07	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR PROPERTY OF

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.