

Nº 5643

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-31-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1061

SIZE OF PIPE USED 6" up

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 130' 7' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32nd ST. N.W.



SIGNED John E. Humer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5643

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/20 1920RECEIVED OF A. J. DeanaFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED E. C. E. C.TO TAP SanSEWER, ON THE W.OF 327 1/2AVE., TYPE OF STREET Alled
ST.THE PREMISES BEING LOT NO. OFF 207HOUSE NO. 1061

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.