Nº 5646

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

| HOUSE NO. 1857 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | |
|-----------------------------------|--|--------|
| SIZE OF PIPE USED 6 | DISTANCE FROM FIRST MANHOLE DESTRICT STREAM TO DITCH AT CURB LINE AND DEPTH | 7 dech |
| WAS LATERAL AT CURBY | and the second of the second o | , |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR Diana | |
| SHOW BY DIAGRAM RELATION OF LATER | | 3 |
| Jeffenson. | | 21 |
| | Carrier transaction of the straining of | |
| | 1 64. 7'd orfo | 15 |
| war al al a Elan | 112 | |
| INSPECTOR FOR CITY | Y Silverification in its bank in the control of the | |

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Nº 5646

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.