

Nº 5652

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-3-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2867

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

102' 7'deep

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way. W.



SIGNED

John E. Houser

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5652

PERMIT TO TAP SEWER

MASSILLON, OHIO. 7/3 1924
RECEIVED OF Raymond Remley FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED A. J. Brown
TO TAP Sanitary SEWER, ON THE South
OF Lin May Hill AVE., TYPE OF STREET paved
ST. 992 THE PREMISES BEING LOT NO. 992, HOUSE NO. 2867

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.