

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
No. 5657 AND SIGNED WHEN RETURNED.**

DATE INSPECTED 7-14-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1216

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

89' 6' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

11TH ST, N.E.

N



SIGNED

John E. ...
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5657

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/14 1920RECEIVED OF R. RemleyFEE OF \$ 3.00FOR WHICH PERMISSION IS GRANTED Edward J. BughTO TAP SanSEWER, ON THE EOF 11th St EAVE.,
ST.,TYPE OF STREET PavedTHE PREMISES BEING LOT NO. 8361-62HOUSE NO. 1616

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.