FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 1-13-51 HOUSE NO. 1718	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM _		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE U PROWN STREAM TO DITCH AT CURB LINE AND DEPTH	98'	62 Deep
WAS LATERAL AT CURBY YES		gradia algorita	·
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR	Diana	
SHOW BY DIAGRAM RELATION OF LAT		RVED.	N N
		A TOTAL OF THE MARK TO A	
1907. Šarosto artikus ar sekses kārska	8 2 Deep - 5'	in the second section of the second s	•
•	The second secon	Kapasan praka na na M	
	62 Deep	SN. Cus	cb.
SIGNED R.J. Smyde	FILED AT ENG	GINEBR'S OFFICE	Main Sewel
INSPECTOR FOR	CITY	ipline herber	7 - 7
REMARKS:		•	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5661 PERMIT TO TAP SEWER

and the control of th	1/1	a vialina a
	MASSILLON, OHIO,	/ 19
RECEIVED OF	and	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	B Quelle	et garage
A grant		
TO TAPSEWER,	ON THE	
OF AVE. TYPE	OF STREET	1-11-11-11-11-1
THE PREMISES BEING LOT NO. 1013 - 10		13
	· · · · · · · · · · · · · · · · · · ·	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	No. 2323, DULY PASSED BY	THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		
$H^{\prime\prime}$		

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.