

12/9

Nº 5665

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-20-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 634

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 11'

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

ERIE, ST. N.

← N _____



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 8-22-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5665

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/1/51 15RECEIVED OF A. J. DianaFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED The John Igelstrom CoTO TAP SanitarySEWER, ON THE EastOF East StAVE., TYPE OF STREET pavedTHE PREMISES BEING LOT NO. 2301, HOUSE NO. 1034

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Diana

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.