Return to Doc.

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

	•	
DATE INSPECTED 8-14-5/	IF SO HOW AND LOCATION FROM	
	FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1638		• 7 - 4
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE CONTROL OF CONTR	7 dech.
WAS LATERAL AT CURB?	The control of the co	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Diana	: : : : : : : : : : : : : : : : : : :
	ERAL TO WALL OF BUILDING SERVED.	
Windsor Ad	N.C.	Z
entre en la contra de la present	744 j	3
	Construction of the confirmation of the confir	22 / desh.
ing and the second seco		and the second s
1 1 5 1		7 12 A
SIGNED / Lower Colores	TY FILED AT ENGINEER'S OFFIC	CE 8-/8-37/
INSPECTOR FOR CI	Problem Was reciden vi problem in din	
REMARKS:		

Nº 5667

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

MASSILLON, OHIO, DIT
RECEIVED OF A Lana FEE OF \$200
FOR WHICH PERMISSION IS GRANTED A. 7/aml
TO TAP, SUNITARY SEWER, ON THE PART
of Andson Panes Type of STREET paria
THE PREMISES BEING LOT NO. 2495 + Ot 8494, HOUSE NO. 1638

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A LANCA

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.