Nº 5673

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DAT	E INSPECTED $8-5/-5/$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	204	8'deeds
HOL	JSE NO. <u>92</u> /			
SIZE	OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS	S LATERAL AT CURB?	and the second s	A Company of the Comp	
WAS	S ATTACHED TO MAIN	— NAME OF CONTRACTOR	iandia	
SHC		TERAL TO WALL OF BUILDING SER	VED.	
	15 TH 5T.	5. W	14	
	<u> </u>			
	 Control of a way with the population of the populatio	13. Westerland from the South Specific Country of the Country South States of the S		
			15	L8181/204
: SIGI		mur FILED AT ENG	INEER'S OFFICE	7/8/5/
REM	INSPECTOR FOR	comy of good first for any and disposed grad		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5673 PERMIT TO TAP SEWER
Masallon, OHIO, 8/21/57
FOR WHICH PERMISSION IS GRANTED LA CONTROL OF THE O
TO TAP SQUELAGE SEWER, ON THE JURIST
of 15 ANN AVE., TYPE OF STREET And Sunfa
THE PREMISES BEING LOT NO. 8275-8276, HOUSE NO. 921 V

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC

IAME OF CONTRACTOR (1) / 1 ana

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.