## Nº 5674 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-30-51	IF SO HOW AND LOCATION FROM 1907	9. dech
HOUSE NO. 720	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURBI	and the second of the second o	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR REMIEV.	
SHOW BY DIAGRAM RELATION OF LAT		
Hillside	PL. 5.W.	4
	and the control of th	5.4
iki di kacamatan da kacamatan da Kacamatan kacamatan da kacamatan		4
	The state of the control of the state of th	5%)
	9'deel	
	190	12
SIGNED Wohn Chan	FILED AT ENGINEER'S OFFICE	55
INSPECTOR FOR C	The differential carbonistics of gentlefact to chick principles.	

## PERMIT TO TAP SEWER

Signature State of the State of
Massillon, Ohio, 15
(No 1 (No Duning or
RECEIVED OF FEE OF SE
and the second of the second o
FOR WHICH PERMISSION IS GRANTED W
TO TAP Santan Lewer, ON THE last
of Hellside PIMAVE. TYPE OF STREET dist
THE PREMISES BEING LOT NO. 1033 7 0, L. 266, HOUSE NO. 720
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RIU ES OF THE DEPARTMENT OF PUBLIC SERVICE

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Name of Contractor\_\_\_\_\_

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.

2015 - Innat S.W