

Nº 5684

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-4-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

73' 8' deep

HOUSE NO. 2778

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way. W. ↑



SIGNED John Ehmer
INSPECTOR FOR CITY

0 95'

FILED AT ENGINEER'S OFFICE 7/29/51

REMARKS:

45.
Nº 5684

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO

9/6/51

RECEIVED OF

Raymond Remley

FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED

Joseph Heinen

TO TAP

sanitary

SEWER, ON THE

north

OF

Lin May Rd

AVE.
ST.

TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

Q7 178

HOUSE NO.

2778

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.