FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-18-51	_ 1F SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM _	346	7 dech
HOUSE NO.	·		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
	- - NAME OF CONTRACTOR	09815	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SE	RVED.	
Singing Brook	k, Dr.	7.	
en en gran de la semble de la merchaniste de la companya de la companya de la companya de la companya de la co La companya de la co	74		
serbe surger before a north of the dust of the			
		25	9406
SIGNED Ochn Edward	FILED AT EN	GINEER'S OFFICE	124151
INSPECTOR FOR C		Deir d Brieffey	A STATE OF THE STA
REMARKS:			

5686

Nº 5686 PERMIT TO TAP SEWER

MASSILLON, OHIO, 15 RECEIVED OF FEE OF \$5 FOR WHICH PERMISSION IS GRANTED SEWER, ON THE AVE., TYPE OF STREET THE PREMISES BEING LOT NO. HOUSE NO. WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.