## 5687

### FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-19-51	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. //				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	991	4 death	
WAS LATERAL AT CURB? Yes		ing sa		
WAS ATTACHED TO MAIN Y & 5				
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SE	RVED		
16 TH ST. S.W.		7		
The state of the s		6:464		2 - 10 - 1
<u> </u>		# 1 m		
			99	. 1
1 1 1 1		And the second s	and the state of t	_()
SIGNED John Lann	FILED AT EN	GINEER'S OFFICE	9/24/81	
INSPECTOR FOR CIT	The Control of the March 1989		<del>, ,</del>	
REMARKS:				

#### RECEIVED THE DIRECTOR OF PUBLIC SERVICE

# Nº 5687 PERMIT TO TAP SEWER

	11 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -
	RECEIVED OF FEE OF \$
, -	TAPSEWER, ON THE
oF	1/30 pt ( ) + I to a married a reason of the first of
TH	E PREMISES BEING LOT NO
	ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIDES OF THE DEPARTMENT OF PUBLIC SERVICE.
N/	AME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.