

5
38
✓

Nº 5689

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 737

SIZE OF PIPE USED 6" up DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 147' 8' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

17th ST. N.E.



SIGNED John Chmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 7/24/51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 5689 PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/17 1915
RECEIVED OF A. J. Deane FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED Ohio Electric Light & Power Co.
TO TAP San SEWER, ON THE W. P. W.
OF 177 R. 10 E AVE., TYPE OF STREET West
THE PREMISES BEING LOT NO. 7949 HOUSE NO. 757
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Deane

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.