

Nº 5691

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-29-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 224

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 174' 4' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Entle Ave N.E.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/29/51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5691

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/17 1913

RECEIVED OF A. D. Deane

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Harry Ross

TO TAP San

SEWER, ON THE N

OF East 10th E

AVE.,
ST.,

TYPE OF STREET Relief

THE PREMISES BEING LOT NO. 7643

HOUSE NO. 224

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deane

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.