

Nº 5705

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-4-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1812

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 239' 6' deep


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way, E.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-17-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5705

PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct 1 1920RECEIVED OF Geo. CarnellFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Same.TO TAP SanSEWER, ON THE W.OF Lincoln Way EAVE.,
ST.,TYPE OF STREET Paved.THE PREMISES BEING LOT NO. 9133HOUSE NO. 1812

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.