

Nº 5707

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE, INSPECTED 10-6-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1918

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Piana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-17-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 5707 PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/5 1921

RECEIVED OF A. J. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Joseph James

TO TAP San

SEWER, ON THE W N.

OF Hick N.E.
Beverly Rd N.E.

AVE., TYPE OF STREET

McCadd

THE PREMISES BEING LOT NO. 1286

HOUSE NO. 131

10635, 10634, Lot 10633

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.