

Nº 5708

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-9-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 818

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

219' 8' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Franklin Ave N, E.



6' deep

40

8' deep

3

219

SIGNED

John E. Hines
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-17-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 5708

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/8/51RECEIVED OF E. B. MaysFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED E. B. MaysTO TAP sanitarySEWER, ON THE northOF Franklin RdAVE.
ST.TYPE OF STREET hard surf.THE PREMISES BEING LOT NO. 8063HOUSE NO. 818

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Wiana

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.