## 5709 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-11-51		
HOUSE NO. 407	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	[ide c]
WAS LATERAL AT CURBI	<u>and an agraph of the state of </u>	All the
WAS ATTACHED TO MAIN VES	- NAME OF CONTRACTOR Diana	
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.	1
26 th 57,	N. W	6
A STATE OF THE STA	A CONTRACTOR OF THE CONTRACTOR	<b>5 V</b> 1
		6'dech 9
and the		A1/119
INSPECTOR FOR	CITY  VALUE OF THE CONTROL OF THE CO	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	Nº 5709 PERMIT TO TAP SEWER
	HORSELLON, OHIO,
la :	RECEIVED OF JANEAN AS HELDER FEE OF \$ 2
	FOR WHICH PERMISSION IS GRANTED TO THE TOTAL TO THE TOTAL OF THE TOTAL
ا به ودد	TO TAPSEWER, ON THE
· .	OFAVE. TYPE OF STREET
. 1	THE PREMISES BEING LOT NO. 1600, HOUSE NO. 407
	Work to be done in accordance with Ordinance No. 2323, duly passed by the City Coun Rules of the Department of Public Service.

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.