

Nº 5714

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-26-51

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2813

SIZE OF PIPE USED 6" 4'

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH 71' 6' deep



WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way W.



SIGNED John Emerson

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

# OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5714

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 10-25, 19

RECEIVED OF Raymond Remley FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED St. Barbara's Church

TO TAP Sanitary SEWER, ON THE South

OF Lincoln Way W AVE., TYPE OF STREET Paved

THE PREMISES BEING LOT NO. Pt 01 243, HOUSE NO. 2813

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remley

**Note.** This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.