## Nº 5716 AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-2/-5/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	143	9'dech
HOUSE NO. 924			•
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB7	en e	r <del>f</del> orma (1964) og forsk forsk forsk	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR RE	mley	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SEF	RVED.	•
9 TH 57.	5.14	8	•
and the second s		7800	
		*	
<u> </u>			
•			
		9400	143
Out thouse			tapped 0
SIGNED INSPECTOR FOR CIT	- <b>Y</b>	GINEER'S OFFICE	7-31-57
REMARKS:	Traditional consultation of the	18-8 - 18-1 19/1 1/1 	

## THE PERSON AND THE REPORT OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 5716 PERMIT TO TAP SEWER

4.	一大,你你没好你的我的什么事。			1 4	
e e e e e e e e e e e e e e e e e e e	$\sim$ $\sim$	_M	ASSILLON, OHIO,	10-2	19
Received of	- Kara	and K	enden	FEE	OF 5 2 CT
	$\theta$	and the second	June 1	garan kat	1.3%
FOR WHICH PERMISSI	ON IS GRANTED		The Contract of the		
TO TAP	Merte	SEWER, OI	THE 2.A		<u> </u>
of (11)	sw r	AVE., TYPE O	F STREET BALL	ed	
THE PREMISES BEING		•		1	
Work to be done i	N ACCORDANCE	WITH ORDINANCE !	10. 2323, DULY FA	ASSED BY THE	CITY COUNCIL
RULES OF THE DEPAR	TMENT OF PUBLIC	SERVICE.		•	
	<b>'</b> )	$\cap$			
NAME OF CONTRACTO	, Kann	work K	endu.		
	0		$\overline{\Lambda}$	New,	

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.