

Nº 5717

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-12-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 519

SIZE OF PIPE USED

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way. W.



SIGNED

John E. Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10/31/51

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5717

PERMIT TO TAP SEWER

MASSILLON, OHIO.

10-25 19

RECEIVED OF

Raymond Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Marchand's Market (Sewer)

TO TAP

Sanitary

SEWER, ON THE

South

OF

Lincoln Way W

AVE.,

TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

436 and 437

HOUSE NO.

519

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.