Nº 5722 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3 - L -51	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO.			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 7 DEED.		
WAS LATERAL AT CURB? YES	The state of the control of the state of the		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR REMIEW		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
A service of the serv			
	6"X 4" Y		
	17'Deep		
	A. Curb		
SIGNED R. J. Smile	FILED AT ENGINEER'S DEFICE 1273		
REMARKS:	audinam Mest for Mark in paid that he three		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

where ${f N}_{2}^{0}$ is ${f 5722}$ is the section.

PERMIT TO TAP SEWER

그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그		
The state of the s	Мазыцгом, Оню,	10-25 19
V 4 4	Kenley	
RECEIVED OF	M. A. C. C. A.	FEE OF \$
FOR WHICH PERMISSION IS GRANTED TAULT	ochm = Ste	Julius and a series of a
TON WHICH FERMIOSION IS CHARTED		
TO TAP DENTELLY SEWER	ON THE MOST	and the second second
OF COUNTY AVE. TYPE		
THE PREMISES BEING LOT NO. 3521	, HOUSE NO	7777/44/11/11
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	E No. 2323, DULY PAS	SED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR	12 may	

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.