

Nº 5726

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-14-51

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM

97 -

5' deep

HOUSE NO. 318

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1ST ST, N.E.



SIGNED

John E. ...
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10/21/51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5726

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10-25 19

RECEIVED OF Raymond Remy FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Remy + Perrow

TO TAP Sanitary SEWER, ON THE East

OF Lot 5 + NE. AVE., TYPE OF STREET Paved ST.,

THE PREMISES BEING LOT NO. 630, HOUSE NO. 318

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remy

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.