## Nº 5744 AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-9-51	IF SO HOW AND LOCATION FROM	
The second secon	FIRST MANHOLE DOWN STREAM	
HOUSE NO. 8/4		
**************************************	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
SIZE OF PIPE USED	CURB LINE AND DEPTH 10 6	6'6" dech
WAS LATERAL AT CURBI Yes	julija i kristini kaliji arktitini kilopia kristini ala	
WAS ATTACHED TO MAIN Y & S	NAME OF CONTRACTOR Hann	4.
SHOW BY DIAGRAM RELATION OF LATE		1
Lake	Ave. W. E	4
and the second s	mulita 🖍 (1) ja ja kan kan kan kan kan kan kan kan kan ka	1/ 1/8
		الماء
a king kacamatan dan panjarah basar basar basar bina bah	The state of the s	7/
	A representation of the way and grammer of the for	2 / 1
·	101	23
	The state of the s	
SIGNED of Chan	FILED AT ENGINEER'S OFFICE	1-27-51
INSPECTOR FOR CIT	Confirmate or traditional published to show	
REMARKS:	in the second of the control of the second o	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 5744 PERMIT TO TAP SEWER

a season en emperar en la calega racina a	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	MASSILLON, OHIO,19
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	J Crone
TO TAPSEWER, (	ON THE
OF AVE. TYPE	OF STREET
THE PREMISES BEING LOT NO. 55 45-46	HOUSE NO.
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
Name of Contractor	

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.