FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-28-51	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1415	DISTANCE FROM FIRST MANHOLE 19 1997/98 1729
SIZE OF PIPE USED 6	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN \(\frac{1}{\mathcal{L}\mathcal{L}}\) SHOW BY DIAGRAM RELATION OF LATER	NAME OF CONTRACTOR DIANA
	10 WALL OF BUILDING SERVED.
Agreed the first to be seen the grant that the second of t	N Deep 3
SIGNED R. F. Smyder	Main Sewer - 14' Deep FILED AT ENGINEER'S OFFICE 12/5/5/
REMARKS: Lateral In 3	shate rock af Main 2B

Nº 5747

PERMIT TO TAP SEWER

the contract of the contract o
MASSILLON, OHIO, 19
RECEIVED OF 11-1. // / ana FEE OF \$ 2-
RECEIVED OF FEE OF \$
FOR WHICH PERMISSION IS GRANTED 1100 ACKNOWL
1 4
TO TAP Sanday SEWER, ON THE South
I the I Did Africania and a second and a second
OF TOPEN MY NAVER TYPE OF STREET
THE PREMISES BEING LOT NO. 7203-7204, HOUSE NO. 1415

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR (1) / Juliana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.