Nº 5756

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-5~ 52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 9/5	
SIZE OF PIPE USED 4"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY Yes	The filter and the company of a company of the comp
WAS ATTACHED TO MAIN 155	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
Andrew Ave	e NE. 12
	7 Held
producti de la esta de locales estas la calendar de la esta de la composición de la esta d	re la la regió ana, en las presentes de la esta de la región de la reg
	The contract of the section of the contract of
	5000 11 385'TO E.B.L
and the	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 3/10/52
REMARKS:	multiperid of teriples at 2 of them in after

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5756

PERMIT TO TAP SEWER

en e	Massillon, Ohio,	3/, 1
RECEIVED OF a Adam		FEE OF S
FOR WHICH PERMISSION IS GRANTED	Rikkle	Page same ded
TO TAP Aland SEWER.	ON THE	D 22 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
of Ave. Type	OF STREET	and surface
THE PREMISES BEING LOT NO. 151	18/3, HOUSE NO.	915
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	No. 2323, DULY P	ASSED BY THE CITY COUNCIL

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR ALAMA

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.