

Nº 5758

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-12-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1027

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 32' 7' deep
CURB LINE AND DEPTH



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Hamm

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3RD ST. N.E.



SIGNED John E. Linn
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

3/25/52

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5758

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/12 1919

RECEIVED OF Fred. Lann FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED John Fred. Lann

TO TAP San SEWER, ON THE W

OF 3rd 77 E AVE., TYPE OF STREET Hard surface

THE PREMISES BEING LOT NO. 7714 HOUSE NO. 1027

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Lann

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.