

No. 5771

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-3-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 843

SIZE OF PIPE USED 6" oh DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 7' 3' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Hamm

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

11th ST. S.E.



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 9/8/52

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
Nº 5771 PERMIT TO TAP SEWER

MASSILLON, OHIO, Mar. 29 19

RECEIVED OF Maxine Ross FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED Same

TO TAP Sanitary SEWER, ON THE West

OF 11th St S.E. AVE., TYPE OF STREET Hard surface

THE PREMISES BEING LOT NO. 10086 HOUSE NO. 843

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Hanne

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.