FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N^{o}_{1} 5777 AND SIGNED WHEN BETTIENED AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-21-5	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 36	7' dech
WAS LATERAL AT CURBI	ong Borold (1997) on a sweet for the west design will design. ✓	•
WAS ATTACHED TO MAIN C.S	NAME OF CONTRACTOR DIAMA	
Amhurst	RAL TO WALL OF BUILDING SERVED.	6
	and the state of t	40
	30	/10
SIGNED COLOR	FILED AT ENGINEER'S OFFICE S	73/32
INSPECTOR FOR CIT	nother the making to make the property of	* T

Nº 5777

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Limente de directo de la companio del companio de la companio del companio de la companio del la companio de la companio del la companio de l	MASSILLON, OHIO, Upil 21 19
RECEIVED OF a g D sound	FEE OF \$ 2-1
FOR WHICH PERMISSION IS GRANTED	Carry
TO TAP SEWER	ON THE East
an nakalan kanala sakala ka manaka mana ka ka mata da 🚛 na berbanah bana bana bana da da da baharan bana bana bana bana bana bana bana	of STREET David
	1.00
THE PREMISES BEING LOT NO. 4/0 2 6	HOUSE NO. Corner of Leche Y limit
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E No. 2323, DULY PASSED BY THE CITY COUNCI

NAME OF CONTRACTOR a 9 19 Manie

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.