

Nº 5781

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-20-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 756

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 184' 7' deep

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Avon CT. S.E.



SIGNED Johan Elmer

INSPECTOR FOR CITY

Lamp Hole.

FILED AT ENGINEER'S OFFICE

REMARKS: Sewer in Curley Ct.

7/8/52

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5781

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/24 1924

RECEIVED OF A. J. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Stanley W. Wansick

TO TAP San

SEWER, ON THE E.

OF Union Ave.

AVE., TYPE OF STREET der

THE PREMISES BEING LOT NO. 4298-99

HOUSE NO. 756

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.