5790 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-3-	15 SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	7'dech
HOUSE NO. 1407	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED 4"	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	The state of the s	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR KEUM	4
	OF LATERAL TO WALL OF BUILDING SERVED.	·
Reupe	+ Kve, N.E.	8
i di ili de la	en de la companya de La companya de la co	PL
samme of Difference for some state of		/ 0,
	un maan sa esta uma a montas laten ee uurapin laevuleetin oli oli oli ee ela oli aasa 13 oli ee ah oli	5/
	rogenisas ir ir ir ir medining salah mengani salah mengani salah mengani salah mengani salah mengani salah men	10/ 178
1 8		10/3
SIGNED (17 12 11 (INSPECT	OR FOR CITY	3/10/22-
REMARKS:	in the soft markles who all disolption be industrial for all tow-	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5790 PERMIT TO TAP SEWER

Massillon, Ohio, 5/5/57
RECEIVED OF C. P. MASSILLEN, ORIO. FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED C.D. Muyer
TO TAP_ Sanutary SEWER, ON THE West
of Renger Blad & Eave. Type of STREET dist
THE PREMISES BEING LOT NO. 10919 , HOUSE NO. 1407

ORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.