Nº 5800

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-6-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 529	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	11 dech
WAS LATERAL AT CURB?	CURB LINE AND DEPTH	11 a cep.
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR DIANA	
SHOW BY DIAGRAM RELATION OF LAT	TERAL TO WALL OF BUILDING SERVED.	
Webbl	Ave, S.W	10
	Street in we been as interest with well with the Street St	
	1	000-00 transique (2000-00) full are enterent (2000-00) force and enterent (2000-00)
SIGNED SIGNED INSPECTOR FOR	ght and ignority of trady years problem in the com-	5/10/52
REMARKS: 3 CH/ CF 171	rear in alley.	

Nº 5800

PERMIT TO TAP SEWER

RECEIVED OF 10 sand	FEE OF \$	2
그는 그를 가는 사람들이 되었다. 그는 그는 그는 그는 그는 그를 가는 것이다.	ucaprovo.	:
TO TAP Sanitary SEWER, ON THE	south	2
OF Well I W AVE. TYPE OF STR	and the regularity of the first	i
THE PREMISES BEING LOT NO. 5536	HOUSE NO. 529	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR DECENOR

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.